


FIG-2

FIG-3






FIG-4




FIG-5




FIG-6




FIG-7




FIG-8




FIG-9












FIG-10








FIG-20




FIG-19




FIG-22




FIG-21

FIG-23





FIG-24



FIG




FIG-26





FIG - 25

FIG-27






FIG-28








FIG-29

FIG-30






FIG-37




FIG-37




FIG-36




FIG-38

FIG-39




FIG-40




FIG-42




FIG-41




FIG-43




FIG-44




FIG-45





FIG-46




FIG-46A

FIG-47

O = SPACERS
X = HAMMERS

